



1

Install the canopy. Please refer to Bocci's installation instruction for more detail.




2

First, install the inner circle of pendants in the center of the canopy. Please refer to Bocci's installation instruction for more information.




3

Install the spreader bars one at a time, beginning with the highest and ending with the lowest. For each bar, attach a pair of coaxial cables opposite from one another from the center of the canopy into the middle two slots of the spreader bar. Secure each spreader bar in this way until they are all attached and level.



4

To attach the coaxial cable to the spreader bar, slide the cable into the appropriate slot in the spreader bar. Slide the split tube down so that it protects and insulates the wire inside the bar. Ensure the tube is flush to the bottom of the bar, which will leave it protruding 1-2mm from the top. Tighten the setscrew to secure the coaxial cable at its new length. Do not over tighten.



5

Install the remaining pendants to the canopy and then to their matching slots in the spreader bars by working from the center outwards.

For additional assistance, please contact Bocci:

Vancouver  
sales@bocci.ca  
www.bocci.ca

Berlin  
europe@bocci.ca  
www.bocci.ca

COAXIAL CABLE

# Spreader Bars

Design by Omer Arbel  
PRODUCT INSTALLATION INSTRUCTIONS

© 2019, Bocci Design and Manufacturing Inc. All rights reserved. Any inquiries should be directed to: info@bocci.ca

**BOCCI**