


Installation should be made by an electrician. Make sure that the circuit breaker is shut down at all time during the installation.

Necessary tools:

- Wall electrical box with screw
- Screwdrivers
- Wire connectors



Put the canopy back up and tigthen the ring.

